



## TN129 PSTN Interface Connector Warning

### PSTN Interface Connector Warning

When using a Blade equipped with a 476-175 PSTN Interface module, **DO NOT** plug the RJ-11 connector from the phone line directly in to the Blade port, as this can possibly damage the pins of the Blade connector. Obtain an RJ-45 to RJ-11 adaptor, coupler, or an RJ-45 to RJ-11 cable.

In the photo below, you can see the adaptor plugged in to a Blade port and the telephone line cord plugged in to the adaptor.



Another option is to wire directly from the PSTN point through a distribution frame and connect to the M4x with a CAT5 type cable.